

## CERTIFICATE OF COMPLIANCE

according to

EN 55022 : 1998/ A1:2000 (Class B)  
EN 61000-3-2 : 1995/ A1/ A2:1998/ A14:2000  
EN 61000-3-3 : 1995/ A1:1998

EN 55024 : 1998  
IEC 61000-4-2 : 1995/ A1:1998/ A2:2000  
IEC 61000-4-3 : 1996/ A1:1998/ A2:2000  
IEC 61000-4-4 : 1995/ A2:2000  
IEC 61000-4-5 : 1995/ A2:2000  
IEC 61000-4-6 : 1996/ A2:2000  
IEC 61000-4-11 : 1994/ A2:2000


Applicant	TRENDware International, Inc.
Address	3135 Kashiwa Street, Torrance, CA90505 U.S.A.
Equipment	4-Port ADSL Modem Firewall Router
Model No.	TW100-BRM504

### I HEREBY CERTIFY THAT :

The measurements shown in this test report were made in accordance with the procedures given in **EUROPEAN COUNCIL DIRECTIVE 89/336/EEC**. The equipment was *passed* the test performed according to **European Standard EN 55022:1998/ A1:2000 (Class B), EN 61000-3-2:1995/ A1/ A2:1998/ A14:2000, EN 61000-3-3:1995/ A1:1998 and EN 55024:1998 (IEC 61000-4-2 : 1995/ A1:1998/ A2:2000, IEC 61000-4-3 : 1996/ A1:1998/ A2:2000, IEC 61000-4-4 : 1995/ A2:2000, IEC 61000-4-5 : 1995/ A2:2000, IEC 61000-4-6 : 1996/ A2:2000, IEC 61000-4-11 : 1994/ A2:2000 )**.

The test was carried out on Oct. 23, 2003 at Electronics Testing Center, Taiwan.

Signature



Anson Chou / Manager