



USB to Parallel 1284 Converter

TU-P1284 (v2.0R)

- Connect parallel port printers to a USB port
- Easy plug and play installation
- Supports multiple operating systems

TRENDnet's USB to Parallel 1284 Converter allows you to connect a parallel printer to a USB port on your laptop or desktop PC.



Easy Setup

Simple installation in seconds




Operating Systems

Compatible with Windows® and Mac® operating systems




Computer Connection

Integrated flexible 2 m (6.6 ft.) USB cable accommodates most installation scenarios




USB

Supports USB 1.1 and compatible with USB 2.0 and USB 3.0 ports.



IEEE 1284 Centronics


Allows users to reuse legacy parallel printers with USB enabled laptop and desktop workstations.



Flexible Connector

Integrated flexible 2 m (6.6 ft.) USB cable accommodates most installation scenarios.

Networking Solution



Specifications

HARDWARE

Interface

- USB 1.1 Interface type A
- IEEE 1284 centronics 36 male

System Compatibility

- Windows® 10, 8.1, 8, 7, Vista, XP
- Mac OS® 10.6-10.9

Cable Length

- 2 m (6.6 ft.)

Cable Gauge

- 28 / 24 AWG

Data Rate

- 12 Mbps

Power Consumption

- 500 mA (max)

Weight

- 105 g (3.7 oz.)

Operating Temperature

- Operating: 0°C ~ 40°C (32°F ~ 104°F)
- Storage: -10°C ~ 45°C (14°F ~ 113°F)

Humidity

- Max 85% (non-condensing)

Certifications

- CE, FCC

Package Contents

- TU-P1284
- Quick Installation Guide

